Flag Country | IMO ID Number | Date of ECA First Notice | Location of ECA First Notice | Mame of Ports after First Notice | H#Bahamas | H#9640956 | H#Dec. 30, 2013 | H#Pascagoula, MS | H#Altamira, Mexico

##Altamira, Mexico

Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption ##Pascagoula, MS

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA ##Chevron ##1 ##Dec. 16, 2013

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion ##Already in ECA Zone ##3.5% ##52

Name of First POC Compliance Fuel Oil Available at First POC? ##Pascagoula, MS ##No

Plan to Bunker Compliant Fuel Oil at First POC? ##No LSFO available in Pascagoula, MS or Altamira, MX ##1

Number of fuel suppliers contacted at First POC

Name of Second POC Compliant Fuel Oil at Second POC? Plan to Bunker Compliance Fuel Oil at Second POC? Altamira, MX ##No #No

Number of Fuel Suppliers Contacted at the Second POC? Date of Exit from ECA? Time of Exit from ECA? ##0, Bunkers not available

Dec. 31, 2013 300 Has this vessel operated in the ECA in previous 12 months? Number of Separate Visits to the ECA ##Yes

##4

Number of Ports visited in the ECA Previously submitted ECA0100 forms? Number of Submitted Reports ##4 ##Yes ##1

Designated Corporate Official Name Designated Corporate Official E-mail ##John Sheather

##Jsheather@cslbos.com

Designated Corporate Official Phone Number ##9789221300

Description of Actions to Achieve Compliance
##Vessel will return to load in Pascagoula, MS where supplier Chevron will have a re-supply of LSFO